

# SAFETY BULLETIN

# Stored energy in u-shaped cable bolt packaging

## BACKGROUND

The stackable steel framed packaging of u-shaped cable bolts contains a significant amount of stored energy. This can cause an injury, particularly to the hands, when the cable bolt packaging is undone and the stored energy causes the cable bolt to spring open.

### CIRCUMSTANCES

Workers have identified that releasing the stored energy from the stackable, steel framed packaging of the horseshoe shaped cable bolts is a hazardous task that can cause significant injury. An incident has occurred where a worker sustained an injury to his hands

when he released a u-shaped package of cable bolts and his hand became caught between the cable bolts and the side of the storage pod.

Photo 1: U-shaped cable bolts in yellow steel framed packaging, stored in a pod.

### RECOMMENDATIONS

Mine management should contact their cable bolt supplier to discuss the current arrangements of their cable bolt packaging. This discussion should include collaborative consultation between mine management, workers and the suppliers regarding alternatives to release the stored energy of the cable bolt packaging or how operations can safely transport other cable bolt configurations underground.



**NOTE:** Please ensure all relevant people in your organisation receive a copy of this safety bulletin, and are informed of its content and recommendations. This safety bulletin should be processed in a systematic manner through the mine's information and communication process. It should also be placed on the mine's notice board.

Signed

Rob Regan DIRECTOR MINE SAFETY OPERATIONS BRANCH NSW TRADE & INVESTMENT

View more safety bulletins and search our safety database at <u>www.resources.nsw.gov.au/miner-and-explorers/safety-and-health/safety-bulletins</u>. If you would like to receive safety bulletins by email, enter your contact details at <u>www.resourcesandenergy.nsw.gov.au/info/signup</u>

**Disclaimer:** The information contained in this publication is based on knowledge and understanding at the time of writing. However, because of advances in knowledge, users are reminded of the need to ensure that information on which they rely is up to date and to check the currency of the information with the appropriate officer of NSW Trade & Investment or the user's independent advisor.

Mine Safety Report No: SB15-02 Prepared by: Kylie Newton Phone: 02 4931 6406 Date Published:04/03/15